



Bulletin No.: PIT5871

Published date: N/A

Preliminary Information

PIT5871 Unable To Select Sport Mode

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|---------------------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Chevrolet | Silverado 1500 LTD | 2022 | All | All | All | All |
| GMC | Sierra 1500 Limited | 2022 | All | All | All | All |

| | |
|----------------------------|---|
| Involved Region or Country | North America |
| Additional Options (RPO) | RPO R30 - LT275/65R18 Wrangler DuraTrac Tires or RPO QFV - LT265/60R20 Wrangler Territory MT Tires |
| Condition | Some customers may comment the Driver Mode Control menu list a Sport mode, but it cannot be selected. You will be able to change and select other driver modes like Normal, Off Road, Tow/Haul, etc., but Sport mode can not be selected. |
| Cause | These vehicles should not be equipped with Sport mode. The cause of this condition is an incorrect IPC calibration, which is incorrectly listing Sport Mode in the Driver Mode Control menu, shown below. |



Correction:

GM engineering is working on a fix to update the IPC to remove Sport Mode from the Driver Mode Control menu.

Version History

| | |
|----------|--------------------------|
| Version | 1 |
| Modified | 11/30/2021 - Created on. |



© 2021 General Motors. All Rights Reserved.